

# Hurricane Irene Damage



This satellite image by DigitalGlobe displays the severe damage in Vermont in the town of Killington along US Hwy 4 and Road 100. In the centre, the pavement that has been washed away by high creek waters.

Of note is the washout/slide in the upper right between the houses which covers the road. The center of the image has several businesses surrounded by mud and water. (Image

Courtesy: DigitalGlobe)

---

<https://www.gim-international.com/content/article/hurricane-irene-damage>

---